

[illegible]

0 1000 ft

-  Trichloroethylene (TCE) Detection
-  Trichloroethylene (TCE) Estimated
-  State Superfund Site with TCE
-  Brownfield Site with TCE
-  Remediation Site Boundary with TCE
-  Development Location with Brownfield CoC
-  Development Location without Brownfield CoC
-  Development Location (No Remedial Site)
-  SVI Investigation Phase 1
-  SVI Study Boundary
-  Tax Parcel

Table 1
Development Location Information

Study Boundary (Pink)	SVI Investigation Area (Orange Hash)	Brownfield	Certificate of Completion	TCE Detected at Remedial Site *1	Address
Yes	No	C224350		Yes	320 Nevins Street
Yes	No	C224350		Yes	340 Nevins Street
Yes	No	C224209		Yes	175-225 Third Street
Yes	Yes	C224012B		Yes	477 Smith Street
Yes	No	C224221		Yes	395 Carroll Street - 325 Bond Street
Likely	Likely	C224012		Yes	463 Smith Street
Yes	Yes	C224222		No	563 Sackett Street
Yes	Yes	C224336		No	155 Third Street
Yes	No	C224316		Yes	192 Douglass Street
Yes	Yes	C224367		Yes	251 Douglass Street
Yes	Yes	224051		Yes	545 Sackett Street
Yes	Yes	C224329	Yes	No	577-581 Union Street
Yes	No	C224219	Yes	Yes	450 Union Street
Likely	No	C224368		No	167-174 Fourth Avenue
No	No	None Identified		No	52 Fourth Avenue
Yes	Yes	None Identified		No	209-215 Third Avenue
Likely	No	None Identified		No	491 Baltic Street
Yes	Yes	C224373		No	224 Third Avenue

*1 No TCE detected at Remedial Site or on parcel(s) where no Remedial Site was identified

Table 2
Reference Reports

Map Group	Facility ID	Report Link
A	C224316	Report.BCP.C224316.2012-06-01.Site Investigation Report-TRC.pdf
B	C224367	Application.BCP.C224367.2022-06-21.Complete BCP Application.pdf
C	C224222	Application.BCP.C224222.2012-07-01.Remedial Investigation Report-Fulton MGP.pdf
D	C224080	Report.BCP.C224080.2022-01-13.RI Report.pdf
E	C224220A	Report.BCP.C224220A.2023-04-14.Site Characterization - Goundwater and Soil Vapor.pdf
F	C224329	Application.BCP.C224329.2020-10-02.Supplemental Investigation Report.pdf
G	C224309	Report.BCP.C224309.2020-10-27.Remedial Investigation Report Final.pdf
H	C224225	Report.BCP.C224225.2023-02-02.335 Bond Street Revised Final Remedial Investigation Report.pdf
I	C224220	Report.BCP.C224220.2019-08-16.Final RIR (Labs and Pre Reports Separate).pdf
J	C224173	Report.BCP.C224173.2014-11-24.RIR.pdf
K	C224219	Report.BCP.C224219.2017-05-05.Report.BCP.C224219.2017-05-17.RIR_FINAL.pdf.pdf
L	C224221	Report.BCP.C224221.2022-08-15.Remedial Investigation Report
M	C224174	Report.BCP.C224174.2014-09-08.RIR.pdf
N	C224346	Report.BCP.C224346.2021-11-01.Subsurface Investigation_Report.pdf
O	C224209	Report.BCP.C224209.2019-12-02.Final RIR.pdf
P	C224100	Report.BCP.C224100.2006-10-31.Final_RIR_Part1of6.pdf
Q	C224012B	Report.BCP.C224012B.2005-10-28.Final Remedial Investigation Report from VCP.pdf